


Cutting & Folding

options


Robert Heithaus
601.434.0026
rheithaus@hawkconverting.com



Half cut






When you cut, cut beyond the middle of the board.




V-cut

(thick material only)






Deeper cut needed than when creating half cut. This prevents tension on the fold.

Creasing



Multiple lines.



We always recommend the use of a creasing matrix.

The number of crease lines depends on the thickness of the board, the angle of the fold and equipment used to create the fold.

General rule: The thicker the material, more crease lines required.